


Drawing 1

REAR




SIDE


SIDE

FRONT

Drawing 2





Drawing 3



FRONT


Drawing 4


Mount the power switch with solder lugs toward the chassis opening.



Drawing 5

FRONT





Drawing 7

